



© 2009 R.J.F.

This picture shows a trial patch of Copperplus that was applied to a tug that was moored in Fowey harbour for two years. When slipped the Copperplus was virtually clean while the remainder of the vessel has a thick covering of growth of all types. The remainder of the vessel has been coated with a well known brand of commercial antifouling.